




Caution

A spacer of the suitable thickness must be attached on the standard BT,IT,or CAT spindle flange .
Do not use BLOCK TOOLINGS on the standard BT,IT,or CAT spindle without a spacer .

KIND		TITLE		CUSTOMER		
SK10-1HB		Slim Chuck with Center Through				
MACHINE MODEL		CODE NO.		DESIGNED	CHECKED	APPROVED
		MCAT50-SK10C-165U		NAKANO		
SCALE	1/1	DIR-NAME SKA1				
DATE	2012.02.17	DRWG NO. SKA11-37004/0				